Rocktov.

Mary A. Gade, Director

2200 Churchill Road, Springfield, IL 62794-9276

217/524-3300

May 31, 1996



CERTIFIED MAIL 7 363 759 165

Sundstrand Corporation
Attn: Mr. James Barry
4949 Harrison Avenue
Post Office Box 7003
Rockford, Illinois 61125-7003

Re: 2100300038 -- Winnebago County Sundstrand Aerospace (Plant 6)

ILD046583993 Log No. C-581-M-4

Date Received: May 3, 1995

RCRA - Closure

ROCKFORD REGION

JUN 20 1996

Environmental Protection Agency

Dear Mr. Barry:

This letter is in response to the certification of closure submitted by David S. Retzlaff, Sundstrand Aerospace, for the hazardous waste pile at the above-referenced facility in Rockford, Illinois. This certification, signed by a representative of the owner/operator, David S. Retzlaff, and an independent registered professional engineer, Jeffery L. Pope, P.E., indicated that the subject hazardous waste management unit had been closed in accordance with the plan approved by the Agency on January 21, 1992.

The subject hazardous waste management unit was inspected by a representative of the Agency on April 8, 1996. The inspection revealed that the unit was closed in accordance with the approved closure plan. In addition, a review of the closure certification and accompanying closure documentation report also indicates that the unit was closed in accordance with the approved closure plan. Therefore, the Agency has determined that closure of the above-referenced unit at the above-referenced facility has apparently met the requirements of 35 IAC 725. Additionally, it appears as though the closure met the closure by removal or decontamination standards of 35 IAC 724.358, thus satisfying the requirements of 35 IAC 703.159 and 703.160. In accordance with 35 IAC 703.121(b), it will not be necessary for Sundstrand to pursue a post-closure permit for the subject waste pile.

As a result of completing closure of the subject hazardous waste management units the Agency has withdrawn your Part A application.

Additionally, this facility must continue to meet the requirements of 35 IAC 722, Standards Applicable to Generators of Hazardous Waste and 35 IAC 728, Land Disposal Restrictions.

Page 2

Finally, it must be noted that Sundstrand should adjust its financial assurance documents on file with the Agency (to meet the requirements of 35 Ill. Adm. Code 725, Subpart G) to reflect the closure of this unit.

Should you have any questions regarding this matter, please contact Michael A. Heaton at 217/524-3312.

Sincerely,

Edwin C. Bakowski, P.E. Manager, Permit Section

Bureau of Land

ECB:MAH:bjh\962324S.WPD

JUM

cc: Robert J. Miller -- Sundstrand Corporation

Elm (Bhil

David S. Retzlaff -- Sundstrand Corporation

bcc: Bureau File Rockford Region Jim Moore

Mike Heaton Bill Sinnott